



Government Of West Bengal
Office Of The Divisional Fire Officer, Paschim Medinipur
West Bengal Fire & Emergency Services
Sepoy Bazar, P.O.- Medinipur, P.S.- Kotwali, Pin:- 721101

Memo no.:FSR/0125186231500258

Date: 25-01-2024

From:
Divisional Fire Officer, Paschim Medinipur
West Bengal Fire & Emergency Services

To: PANDIT ISWAR CHANDRA VIDYASAGAR MISSION
MARICHYA, PARA - KHAN, PS - GHATAL, PO- DANDIPUR, PASCHIM MIDNAPORE, PIN- 721222

Sub: Fire Safety Certificate for the occupancy of an existing LG+G+3 storied Educational building in the name & style of "PANDIT ISWAR CHANDRA VIDYASAGAR MISSION" under group of Educational Building at the premises No.- R.S. Plot No.-1482,1490, J.L. No.-57, Mouza – Marichya, Village-Marichya, Post-Dandipur, Para-Khan, P.S.- Ghatal, Dist.- Paschim Medinipur, PIN-721222.

This is in reference to your application no. 0125189231500132 dated 17-12-2023 regarding the Fire Safety Certificate for the occupancy of an existing LG+G+3 storied Educational building in the name & style of "PANDIT ISWAR CHANDRA VIDYASAGAR MISSION" under group of Educational Building at the premises No.- R.S. Plot No.-1482,1490, J.L. No.-57, Mouza – Marichya, Village-Marichya, Post-Dandipur, Para-Khan, P.S.-Ghatal, Dist.- Paschim Medinipur, PIN-721222.

The performance of the Fire Fighting System as incorporated in the buildings were tested at random and found satisfactorily working condition. In view of the above this office is releasing the Fire Safety Certificate for occupancy of the aforesaid building.

Recommendation:

CONDITIONAL FIRE SAFETY CERTIFICATE ALLOW IN RESPECT OF THIS ESTABLISHMENT SUBJECT TO COMPLY THE FOLLOWING CONDITION WITHIN ONE MONTHS FROM ISSUING OF THIS CERTIFICATE AND INFORM TO THIS END BY WRITTEN FOR REGULARIZATION OF THE CERTIFICATE.

CONDITION, -

1). Install the sprinkler in library and Laboratory maintaining the proper I.S. specification.

EXCEPT THE ABOVE CONDITIONS, THE GENERAL RECOMMENDATIONS ARE AS FOLLOW:-

1. Driveway must be free of any type for obstruction for easy movement of fire appliance no parking will be allowed on the driveway
2. Directional sign and escape route shall be displayed prominently.

[Handwritten Signature]
04-06-26
Principal
Pandit Iswar Chandra Vidyasagar Mission
Affiliated To CBSE
Affiliation No. 2430230, School Code 16009
Marichya :: Ghatal :: Paschim Medinipur

3. To eliminate risk of fire hazards. Good housekeeping both for inside and outside of the building shall be strictly maintained.
4. The interior finish decoration of the building shall be made with low flame spread material confirming I.S. specification.
5. The note of firefighting and evacuation with "Exit Sign" from the building shall be prepared and display at all vulnerable places of the building before taking occupancy.
6. The employees and security staff shall be conversant with installed Fire Fighting equipment of the building and to operating the event of fire and testing.
7. Mock Fire Practice and Evacuation Drill shall be performed periodically with participants of all the occupants of the building.
8. First-Aid Fire Fighting System shall be provided as per I.S. specification.
9. Arrangement shall have to be made for regular checking, testing, and maintenance of all the Fire Fighting Installation in the building to keep them in perfectly good working condition at all the times.
10. If required, the old line shall have to be replace with new line the cable shall always be laid in M.S. conduit pipes continuously bonded to the earth.
11. Periodical flashing of the water from the Hydrants and Hose Reel Hose Pipe Line shall be made to maintain the efficient working performance of above mentioned system.
12. The Fire Safety audit to be conducted a regular interval and to be recorded to the Fire Prevention maintenance register.
13. Existing electrical wiring of the whole building shall have to be carefully checked for anywhere and tear in theme, particularly lines above false ceiling and ducts.
14. A Fire Control Room including a Close Circuit T.V. system will have to be installed which will observe all the floor of the building.
15. Transformer and Switch Gear Room shall be protected with automatic CO2 or DCP Fire Extinguisher confirming I.S. specification.
16. A crew of trained fire man under an experience officer shall be maintained round the clock for safety of the building.
17. The Fire Safety Certificate is valid for three years and has to be renewed triennially from the date of issue of this letter. Triennially a certificate is to be obtained from the Director General, West Bengal Fire & Emergency Services for performance of all the Life & Fire Safety Arrangements and Installations of the Building.
18. No Addition & Alteration without prior permission of West Bengal Fire & Emergency Services, otherwise the Fire Safety certificate will be treated as cancelled.

Signature valid

Digitally Signed.
Name: Bam Kumar Choudhury
Date: 25-Jan-2022 15:15
Reason: Approved
Location: West Bengal

Member Convener Kharagpur TEC, Paschim
Medinipur
West Bengal Fire & Emergency Services

Principal
04.06.26
Pandit Iswar Chandra Vidyasagar Mission
Affiliated To CBSE
Affiliation No. 2430290, School Code-16009
Marichya :: Ghatal :: Paschim Medinipur